


15B

Mitsubishi ASX; Modell 06/2010, 11/2012
Side Protection Pipe 51 / Flankenschutzrohr 51



FITTING INSTRUCTIONS

Montageanleitung • Instructions de montage



30 Minuten


Artikel-Nr:
15B4151 Stainless Steel
15B5151 Steel black

Revision 5: 19.12.2014


www.antec-online.de



SW: 5 mm



Ø 12,5 mm



M6: 2 Nm




1 15B 4151.1R (15B5151.1R) / 15B 4151.2L (15B5151.2L)




a		M6 x25; DIN 912	12x
b		M6; Geto-Well	12x

2 005895



Step 1



12 x Ø 12,5 mm

